Thursday, 12/1/2005 12:56:17 PM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

**Job Number** 

: 25075 : 10253

**Estimate Number** P.O. Number

:NIA

This Issue

: 12/1/2005

: NC

: NIA : 24747

S.O. No. : N/A

: SMALL /MED FAB

:SPE COMMENTORRIOW

**Part Number** 

**Drawing Name** 

: D2183

**Drawing Number Project Number**  : D2183 REV B1 : N/A

: DOOR ASSEMBLY

**Drawing Revision** 

: B1 : MA

Material **Due Date** 

: 12/8/2005

Qty:

5 Um:

Each

Written By

Prsht Rev.

First Issue

**Previous Run** 

Checked & Approved By

Comment

RE COMMENT BELOW

Type

: Est: F 02.04.27 Added D3161-1 Hinge (MPP 2241) NG

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

D2116

Door Panel

Comment: Qty.:

1.0000 Each(s)/Unit Total:

5.0000 Each(s)

Door Panel

D2116

Pick:

Qty Part Number

Description

Batch

516178

4012426

05/12/1

2.0

D2117

Door Panel



Comment: Qty.:

1.0000 Each(s)/Unit Total:

Door Panel

5.0000 Each(s)



Pick:

Qty Part Number

Description

Batch

D2117

Door Panel

133390

SB 05/12/1

3.0

D31611

Hinge 13.5"



2.0000 Each(s)/Unit Total:

10.0000 Each(s)

Comment: Qty.: Hinge

> Pick: Qtv

2

Comment: Qty.:

Part Number

D3161-1

Description

Hinge

Batch

ML**3-**008

05/12/1

4.0

MS20470AD44

Rivet, Universal Head

24.0000 Each(s)/Unit

Rivet

Total: 120.0000 Each(s)

Rivet, Universal Head

Pick:

Qty Part number 24 MS20470AD4-4 Description

Batch M18729

SB 05/12/1

Page 1

Ś

5

80851 N 6655-E-FZSGE ZN / HOOT buch yet about

Date: Thursday, 12/1/2005 12:56:17 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: DOOR ASSEMBLY** Job Number: 25075 Part Number: D2183 Job Number: Seq. #: **Machine Or Operation:** Description: 5.0 SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Drill holes in D3161-1 13.5" hinges using DT 8239 05/12/1 Rivet assembly per Dwg D2183 INSPECT WORK TO CURRENT STEP 6.0 QC5 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING POWDER COATING 7.0 Comment: POWDER COATING Note:Hinges are to be broken back and forth immediately after powder coating to ensure free mobility of hinge. hinge. QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION 8.0 Comment: INSPECT POWDER COAT 9.0 MS20470AD46 Rivet, Universal Head Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Rivet Pick: Part Number Description Batch DV 04/01/24 M17566 MS20470AD4-6 Rivet 10.0 AN960JD6 Washer Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Washer Pick: Qty Part Number Description De ochoilzy 1 AN960JD6 Washer 11.0 D2137 Comment: Qty.: 5.0000 Each(s) 1.0000 Each(s)/Unit Total: Decal - No Step Pick:

. . . I

Date: Thursday, 12/1/2005 12:56:17 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: DOOR ASSEMBLY Job Number: 25075 Part Number: D2183 Job Number: Seq. #: **Machine Or Operation:** Description: Part number Description Batch Qty B23661 'NO STEP' Decal 1 D2137 D24620270 12.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Seal Pick: Qty Part number Description Batch B22749 1 D2462-0270 Seal 13.0 D28541050 Velcro Strip - Looped Comment: Qty.: Total: 5.0000 Each(s) 1.0000 Each(s)/Unit Velcro Strip - Looped Pick: Qty Part number Description Batch De oaloilzy B10189 1 D2854-1-050 Velcro Strip SMALL & MEDIUM FAB RESOURCE 1 14.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per Dwg D2183 Note: Ensure Decal is firmly attached to panel 15.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 16.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 215 17.0 DC Comment: DOCUMENT CONTROL 06/01 Inspection Level 21 5UE Job Completion

Form: rprocess

Page 3

